



30th August, 2017

Ref #: 17-015

Discontinuation Notice: Ionisation Detectors


Notifier is announcing the discontinuation of the Ionisation detectors. Limited stock is available while stocks last.

Item No.	Description
FSI-851AUS (FG-03-012) FS P/No: SSF-I	FlashScan protocol Ion Detector
CPX-751AUS	CLIP protocol Ion Detector

Resources & Support:

Please contact FireSense to discuss specific replacement applications or support questions.

Yours Sincerely,



Robert Kaslik
General Manager

		NSW Head Office	Victoria Branch	Queensland Branch
FireSense Pty Ltd ATF FireSense Trust	Postal Address:	18-20 Brookhollow Ave Baulkham Hills NSW 2153	4/297 Ingles St Port Melbourne VIC 3207	2/225 Queensport Rd Nth Murarrie QLD 4172
ABN: 11 720 788 915	PO Box 7026 Baulkham Hills BC NSW 2153 Australia	Ph: (02) 8850 2888 Fax: (02) 8850 2999	Ph: (03) 9646 4557 Fax: (03) 9646 4558	Ph: (07) 3890 8842 Fax: (07) 3890 8894
www.firesense.com.au				